



Gary L. Doerr, PE

Bridge Management Team Leader, NDDOT



Dale C. Heglund, PE/PLS

Program Director, NDLTAP

Bridge 101

Grand Forks, June 6, 2018


Williston, June 13, 2018



Bryon Fuchs, PE

Local Government, NDDOT

What is a Bridge?




Bridges are . . .

- A Valuable and Critical Asset
 - Major Rehabilitation or Replacement is Costly
 - Detour Routes are often Long
- The Link that Connects the Roadways in our Transportation System





Mur
w
brof




When I
My
ge first

that
a
ge?



**9% of Nation's 614,400 Bridges are Structurally Deficient (NBI, 2016)
(75% of those deficient bridges are on Rural Roads)**

The Silver Bridge was an eyebar-chain suspension bridge built in 1928. The bridge carried US 35 over the Ohio River, connecting West Virginia and Ohio.



46 died
Collapsed December 1967

I-35 W in Minneapolis - 2007

<https://www.youtube.com/watch?v=74JNl5n-Ydl>



<https://www.youtube.com/watch?v=O6ommRCUcsg>



August 1, 2007

Exit full screen

Video Take-Aways

- Design for 75 to 100-year life
 - Fracture Critical
- Bridge in America should not collapse
 - Bridge movement
 - Underfunded and overworked
 - Fatalities
- Lesson – You've got to maintain bridges

Bad Day





BRIDGE PORTAL, MIAMI HERALD VIA AP

Emergency personnel respond after a brand-new pedestrian bridge collapsed onto a highway Thursday at Florida International University in Miami.

Pedestrian bridge falls; multiple people killed

At least eight vehicles crushed when span falls near university

ANJANA GOMEZ LICHON
Associated Press

MIAMI — A pedestrian bridge that was under construction collapsed onto a busy Miami highway Thursday, crushing at least eight vehicles under massive slabs of concrete and steel and killing multiple people, authorities said.

Search-and-rescue crews drilled holes into the debris and used dogs to look for survivors. They had to work carefully because part of the structure was still unsafe.

The Miami-Dade County fire chief says four people have been found dead in the rubble of a collapsed pedestrian bridge in South Florida.

Fire Chief Dave Downey said

on their conditions.

The 950-ton bridge had been assembled by the side of the highway and moved into place Saturday to great fanfare. The span stretched almost 200 feet to connect Florida International University with the city of Sweetwater. It was expected to open to foot traffic next year.

"We have a national tragedy on our hands," Sweetwater Mayor Orlando Lopez said.

Jacob Miller, a senior at FIU, was visiting a friend in a dorm when he heard sirens and horns honking. He went to a balcony and could see rubble coming down.

"I saw there were multiple cars crushed under the bridge. It was just terrible. I saw some people shopping their cars, trying to get out, trying to assess the situation to see if there is anything they could do to help," he said.

The National Transportation Safety Board sent investigators to

investigation after rescue efforts are complete.

An accelerated construction method was supposed to reduce risks to workers and pedestrians and minimize traffic disruption, the university said.

Cristina Rodriguez, a junior at FIU, said the bridge seemed to be built too quickly "to support everything that was on there." Rodriguez was not on campus Thursday but drives through the intersection almost daily.

Renderings of the project showed a tall, off-center tower with cables attached to the walkway to support it. When the bridge collapsed, the main tower had not yet been installed, and it was unclear what the builders were using as temporary supports.

Robert Bea, a professor of engineering and construction management at the University of California, Berkeley, said it was too early to know exactly what happened, but



Really
Bad
Day





- 1968 – National bridge inspection (NBI) program initiated (requiring regular and periodic inspections)
- 1971 – National bridge inspection standards (NBIS) adopted (prescribe how, with what frequency, and by whom bridge inspections must be completed)
- 1987 – Schoharie Creek collapse (scour)
- 2007 – Minnesota I-35W collapse (undersized gusset plate design)

1985 – Adopted 20'+ major structures
and dropped minor structure
inspections

A bridge is a structure with a total opening of greater than 20 feet in length.

Bridges in North Dakota


NDDOT	1,365 $\geq 20'$
City/County	3,287 $\geq 20'$
Total	4,652







Buried Bridges





20' minimum

< 1/2 dia


Minor Structures

Less than 20' in length

Local Practices

Who has bridge
responsibility?

Organized Townships



July 29, 2017 - Bis. TRIB.

Funding remains obstacle for bridges

JOHN HAGEMAN

Forum News Service

County transportation officials say funding remains the biggest obstacle to maintaining North Dakota's bridges 10 years after a busy Minneapolis bridge plunged into the Mississippi River.

Tuesday, Aug. 1, will mark a decade since the Interstate 35W bridge

colla
pron
the r
Fli
bridg
tural
enth
cord
the
tatio
sota
of st
us
nec
safe

But the nearly 56,000 American bridges in that category show "state

and local transportation departments haven't been provided the resources to keep pace with the nation's bridge needs," ARTBA Chief Economist Alison Premo Black said earlier this year.

A Federal Highway Administration spokesman said they now use a three-tier standard instead of the structurally deficient measure. Un-

nant, and of course construction costs have risen," he said. "So we're doing less and less than what we were doing 10, 20 years ago."

West said they rely largely on local property taxes and state revenues to fund bridge projects. They got a "one-time shot arm" with the recent boom in revenues — the county doubt

its normal bridge budget thanks to state oil state budgets have since

ad. We had bridges with to decades. And it's seen one and another one list," West said. "One r, if you want these ve need money. dent Donald Trump an ambitious infrastru m, but the New York d this week that those efforts

alled behind other priorities, such as the federal budget and im-

But state officials are confident in the condition of North Dakota's bridges. Every public bridge in the state is inspected at least every two years, said Jon Ketterling, the bridge

the Minnesota DOT just months after the I-35W bridge collapse. In an interview this week, he said bridge safety will be a priority in his new job.

"Looking down through the bridge

Of the 1,135 bridges on the state highway system, only 23 are structurally deficient, down from 32 in 2007, Ketterling said. That means the vast majority of the deficient bridges are on the urban and county systems, and most county bridges are on "low-volume roads," DOT

mediate funding challenges, "that could change in the next 10 years."

Incoming North Dakota DOT Director Tom Sorel was tapped to lead

state traffic funding projects engineers at the Cass County Highway Department. "The next couple of years could be a little tighter."

West said.

"Our funding has been very stag-

Bridge Cost Estimates



New bridge - \$200/sf

Deck replacement - \$75/sf

Treat deck with silane - \$0.25/sf


Crack seal deck - \$0.10/sf

Williams County Bridge Value

67 Bridges - \$35 Million

Grand Forks County Bridge Value

285 Bridges - \$169 Million




AGT inc. Wholesale Distribution
 3700 West 54 Street, Box 200
 Ft. Worth, TX 76107
 817-841-0800 www.agt.com

NORTH DAKOTA


<u>Class</u>	<u>Total</u>	<u>%</u>
Good	2,323	53%
Fair	1,567	36%
Poor	509	11%

ONSIN

413 52%
725 40%
292 9%




State Bridge Age




■ Number of State Bridges

County Bridges Year Built




Type of Bridges




NBI Condition History of All County Bridges in ND Since 1982

Year	1982	1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999
Total Bridges	4356	4304	4307	4197	4133	4065	4068	4011	3874	3408	3524	3472	3450	3452	3409	3391	3374	3340
Not Deficient	1134	1327	1382	1480	1488	1417	1397	1423	1925	1878	2084	2126	2144	2170	2205	2206	2223	2244
Structurally Deficient	2160	2113	2063	2018	1963	1901	1905	1837	1449	1215	1,121	1021	983	961	892	886	908	851
% SD	49.6%	49.1%	47.9%	48.1%	47.5%	46.8%	46.8%	45.8%	37.4%	35.7%	31.8%	29.4%	28.5%	27.8%	26.2%	26.1%	26.9%	25.5%
Functionally Obsolete	1062	864	862	699	682	747	766	751	500	315	319	325	323	321	312	299	243	245
%FO	24.4%	20.1%	20.0%	16.7%	16.5%	18.4%	18.8%	18.7%	12.9%	9.2%	9.1%	9.4%	9.4%	9.3%	9.2%	8.8%	7.2%	7.3%
Total SD + FO	3222	2977	2925	2717	2645	2648	2671	2588	1949	1530	1440	1346	1306	1282	1204	1185	1151	1096
Total % Deficient	74.0%	69.2%	67.9%	64.7%	64.0%	65.1%	65.7%	64.5%	50.3%	44.9%	40.9%	38.8%	37.9%	37.1%	35.3%	34.9%	34.1%	32.8%


By the Numbers




Percentages






Example of Life Cycle Cost Chart





**BRIDGE OUT
USE ALTERNATE
ROUTE**



ECONOMIC IMPACT OF CLOSING LOW-VOLUME RURAL BRIDGES

Thomas E. Mulinazzi, Ph.D., P.E., L.S.
Professor of Civil Engineering
The University of Kansas
2150 Learned Hall, 1530 W. 15th St.
Lawrence, Kansas 66045
Phone: 785-864-2928
Email: tomm@ku.edu

Steven D. Schrock, Ph.D., P.E.
Associate Professor of Civil Engineering
The University of Kansas
2159B Learned Hall, 1530 W. 15th St.
Lawrence, Kansas 66045
Phone: 785-864-3418, Email: schrock@ku.edu


Eric J. Fitzsimmons, Ph.D.
Lecturer / Post-Doctoral Researcher
The University of Kansas
2159A Learned Hall, 1530 W. 15th St.
Lawrence, Kansas 66045
Phone: 785-864-1921
Email: fitzsimmons@ku.edu

Rachel Roth
Layout Designer
The University of Kansas
Lawrence, KS 66045

Kansas Research



Detour Length – Closures





GhostsofNorthDakota.com

Key Terms and Topics

Bridge – Major Structure

Minor Structure

Design Life

Stream Rules

North Dakota's Laws



Stream Crossings Statutes & Rules

Office of the
North Dakota State Engineer
900 East Boulevard
Bismarck, North Dakota 58505

North Dakota Department of Transportation
608 East Boulevard
Bismarck, North Dakota 58505

January 1, 2015

North Dakota Stream Crossing Standards

89-14-01-03. Design flood frequency. The following table provides the minimum design standard recurrence interval of the event for which each type of stream crossing must be designed. Nothing contained in this chapter is intended to restrict an entity from providing greater capacity.

Type of Crossing	State Highway System						County	
	Urban System		Rural System				Rural System	
	Regional	Urban Roads	Principal Arterial		Minor Arterial	Major Collector	Major Collector	Off ^a System
			Interstate	Other				
Bridges & Reinforced Concrete Boxes	25 year ²	25 year ²	50 year ²	50 year ²	50 year ²	25 year ²	25 year ^{2,3}	15 year ^{2,3}
Roadway Culverts	25 year ²	25 year ²	50 year ²	25 year ²	25 year ²	25 year ²	25 year ^{2,3}	15 year ^{2,3,5}
Storm Drains	10 year ¹	5 year ¹	10 year ²	10 year ²	10 year ²	10 year ²		
Underpass Storm Drains	25 year ¹	25 year ¹	50 year ²	25 year ²	25 year ²	25 year ²		

SELECT A STATE / REGION



NORTH DAKOTA 

IDENTIFY A STUDY AREA

BASIN DELINEATED



Step 5: Your delineation is complete. You can now clear, edit, or download your basin, or choose a state or regional study specific function (if available). Click **continue** when you are ready.

 Clear Basin Edit Basin Download Basin 

What is 100 Year Storm?



A 100-year storm refers to rainfall totals that have a one percent probability of occurring at that location in that year. Encountering a "100-year storm" on one day does not decrease the chance of a second 100-year storm occurring in that same year or any year to follow.[1] In other words, there is a 1 in 100 or 1% chance that a storm will reach this intensity in any given year. Likewise, a 50-year rainfall event has a 1 in 50 or 2% chance of occurring in a year. In addition, each locality has its own criteria for how much rain must fall within 24 hours to classify as a particular rain event. See chart below for other rainfall events.

Recurrence intervals and probabilities of occurrences

Recurrence interval, in years	Probability of occurrence in any given year	Percent chance of occurrence in any given year
100	1 in 100	1
50	1 in 50	2
25	1 in 25	4
10	1 in 10	10
5	1 in 5	20
2	1 in 2	50

Gambling – the odds are always in your favor



50-year storm

Take a card from a deck of 50 cards (a standard deck without the 2 of clubs and 2 of spades). The chance of picking the Ace of spades is $1/50$. If you put the card back in the deck and reshuffle, what are the chances of picking the Ace of spades? Still $1/50$, just like the 50-year storm in a given year.



Pick a card

2012 Storm Duluth, Minnesota 8" Rainfall



Mama always said:
Life was like a box of chocolates.
You never know what you're gonna get."

- Forrest Gump




Bridge Parts




Bridge Components and Terms

- Three Major Bridge Components
 - Deck
 - Superstructure
 - Substructure



Deck

- Portion of the bridge that you drive on



Wooden Deck




Beams as a deck



Superstructure

- Portion of the bridge that lies directly below and supports the deck
 - Beams, girders, truss, arch



Top Flange


Web

Steel Beams
(Girders – Stringers)

Bottom Flange



Diaphragms, Cross Bracing and Supports



A photograph taken from underneath a concrete bridge, showing the structural components. Several horizontal concrete beams (girders) are visible, supported by vertical piers. Transverse concrete members, known as diaphragms, connect the girders at various points. Three orange arrows point to these diaphragms. The word "Diaphragms" is written in yellow text across the upper right portion of the image.

Diaphragms




Splice Plate



Gusset Plate

Truss Bridge Superstructure Elements

Elements of a Truss



Upper Chord

Diagonal


Vertical

Bearing

Lower Chord

Substructure

- Portion of the bridge that supports the deck and superstructure.
 - Abutments, piers





Abutment

Wood Pile Foundations





Steel Pile Foundations

Bearings


- Transfer loads from Superstructure to Substructure
- Provide for movement due to expansion, contraction, rotation
- $\frac{3}{4}$ " expansion with 120° F temp change - 100' bridge




Bearings




Sliding



Rolling/Rocking



Stretching



Swinging

Ice Nose



Wing Wall



Foundations Piling



Metal Railing



Approach Slabs



Key Terms and Topics

Deck
Superstructure
Substructure
Foundation





Beam Shapes














W or H – S or I Shaped

Wide Flange
W or H Beam




© Metals Depot





Bridge Loadings





Truck



Truck pulling one trailer.



Truck pulling two trailers.



Truck-tractor pulling one semitrailer.



"Double
Bottom"

Truck-tractor pulling one semitrailer
and one trailer or semitrailer con-
verted to a trailer with a dolly.




"Triple
Bottom"

Truck-tractor pulling one semitrailer
and two trailers or semitrailers con-
verted to trailers with dollies.




"N" Train

Truck-tractor pulling two semitrailers.



W = COMBINED WEIGHT ON THE FIRST TWO AXLES WHICH IS THE SAME AS FOR THE CORRESPONDING H TRUCK.

V = VARIABLE SPACING — 14 FEET TO 30 FEET INCLUSIVE. SPACING TO BE USED IS THAT WHICH PRODUCES MAXIMUM STRESSES.



Overload Permits

Process Review

Unit Weights

Water = 62.4 #/cubic foot

Gasoline = 42

Ice = 56

Wood = 25 - 50

Gravel = 120

Asphalt/Concrete = 150

Aluminum = 168

Steel = 490

Moment and Shear

Forces in a beam as a load crosses a bridge


Tension and Compression

Material properties and forces

Span length – forces in the beam



Load Rating of Bridges



Dead Load

Gravel

Asphalt

Combination





Overburden



Dynamic Impact Loads

What is it?

Is faster better?

Smooth ride solution

Fracture Critical Bridges





Underwater Inspections

When Are They Needed?



Key Terms and Topics

Dead Loads

Live Loads


Fracture Critical

Bridge Posting – Operating and Inventory



Bridge Inspections





Jake Mertz, with the North Dakota Department of Transportation, maneuvers an aerial lift to reach under the Liberty Memorial Bridge during a routine structure inspection in Bismarck on Monday. The bridge, dedicated on Veteran's Day in 2008, replaced the original 1920 bridge spanning the Missouri River between Bismarck and Mandan. The inspectors look for cracks in the piers, corrosion and light bulb replacement. Burleigh County has 2,985 structures receiving inspections from the department on a two-year rotation. [November 28, 2017 Bismarck Tribune](#)

NDDOT/FHWA Inspections


- Federally mandated
- Includes both NDDOT and City/County bridges
- Normal frequency - 2 years
- Special frequency – 4 years (box culverts)

Who are you going to call???

First Name	Last Name	District	Experience	Certified By	Date Certified	Remarks	Team Leader
BONNIE	BROWN	Dickinson District	15 TE		01-Apr-02	2 WK NHI CO CT '98	TRUE
ANDY	CARLSON	Valley City District	5 TE		01-Apr-17	2 WK NHI CO 2011	TRUE
JAMIE	DEMAREE	Bismarck District	12 TE		09-Jun-09	2 WK NHI CO	TRUE
GARY	DOERR	Main Office	12 PE		22-Mar-02	2 WK NHI CO	TRUE
BRANDON	ELSINGER	Dickinson District	9 TE		29-Oct-04		TRUE
JOHN	FISCHER	Grand Forks District	24 TE		31-Mar-14		TRUE
GARY	HEISLER	Fargo District	14 TE		14-Feb-14		TRUE
DENIS	HORN	Devils Lake District	8 TE		01-Mar-98		TRUE
MEGAN	ISENHOWER	Williston District	4 PE				TRUE
AARON	KELSCH	Fargo District	11 TE				TRUE
BRAD	KERZMAN	Bismarck District	12 TE				TRUE
RANDY	KIRKEVOLD	Fargo District	33 TE				TRUE
SCOTT	LARSON	Retired May 2017	15 TE				TRUE
JOE	LAWSON	Minot District	7 TE				TRUE
JAY	LUTES	Dickinson District					TRUE
MELANIE	MANEVAL	Fargo District					TRUE
TRAVIS	MCCLOUD	Bismarck District					TRUE
JACOB	MERTZ	Bismarck District					TRUE
TONY	NGUYEN	Fargo District					TRUE
GREG	OLSON	Minot District	17 TE				TRUE
DENNIS	ROWELL	Valley City District	23 TE				TRUE
RICHARD	SCHLENKER	Bismarck District	29 TE				TRUE
GARY	TROTTIER	Devils Lake District	15 TE				TRUE
JACK	VINESETT	Grand Forks District	13 TE				TRUE
DIANA	WEBER	Dept of Transportation	8 TE				TRUE
COREY	WEGNER	Valley City District	6 TE				TRUE
RAYMOND	WERRE	Main Office	7 TE				TRUE
TYLER	WOLLMUTH	Bismarck District	4 PE				TRUE



North Dakota Department of Transportation Districts



Structural Inventory and Appraisal Sheet

SI&A Sheet

January 13, 2016		North Dakota Department of Transportation		SEC 409
Bridge Inventory - Structure Inventory And Appraisal Sheet				
Structure Number:	18-113-28.1			chaindate
200 System Designation	3 -- County Off	Classification		
201 Status	Not Deficient	12 Base Highway Network		Not on Base Network
202 Sufficiency Rating	62.00	20 Toll		3 On free road
Identification		21 Maint Responsibility		02 County Hwy Agency
02 Highway District	Grand Forks District	22 Owner		02 County Hwy Agency
03 County	Gr. Forks	26 Functional		Rural, Local
04 City	GRACE TOWNSHIP	37 Historical Significance		5 Not eligible for NHRP
05 Inventory Route	Route On Structure	100 Defense Highway Designation		0 Not a STRAIGHT Hwy
4 County Hwy 1 Mainline	00000 0 N/A (NBI)	101 Parallel Structure Designation		No bridge exists
06 Feats Intersect	CREEK	102 Direction of Traffic		2 2-way traffic
09 Location	2 SOUTH 1 WEST KEMPTON	103 Temporary Structure Designation		Not Applicable (F)
11 Milepoint	0.000	104 Highway System of Inventory Rte		0 Not on NHS
13 LRS Inv Route Subroute	-1 -1	105 Federal Lands Highways		Not applicable
16 Latitude	47d 47' 16.00"	110 Designated National Network		0 Not part of natl netwo
17 Longitude	87d 38' 36.00"	112 NBIS Bridge Length		
GPS Coordinates XY	601621.7 5293501.9	226 Functional Under		
36 Border Bridge	Unknown (F)	Condition		
39 Border Bridge Struct No.		58 Deck		7 Good
Structure Type and Material		59 Superstructure		6 Satisfactory
43 Main Struct Type	Steel	60 Substructure		5 Fair
Stringer		61 Chalk & Chain Protection		7 Minor Damage
44 Approach Struct Type	Unknown (NBI)	62 Culvert and Retaining Walls		N N/A (NBI)
	Unknown (P)	Load Rating and Posting		
45 No. Spans in Main Unit	1	31 Design Load		
46 No. Approach Spans	0	M 16 (H 20) (live load for which structure was designated)		
107 Deck Struct Type	0 Wood or Timber	41 Structure Open, Closed or Posted		P Posted for load
108 Wearing Surface	7 Wood or Timber	63 Operating Rating Method		2 AS Allowable Stress
Membrane	0 None	64 Oper. Rating	HS 14	26 Tons
0k Protect	None	65 Inventory Rating Method		2 AS Allowable Stress
208 Dk Overburden	205	66 Inv. Rating	HS 0	17 Tons
Age and Service		70 Bridge Posting		2 20.0-25.99 below
27 Yr Built	1949 106 Yr Reconstructed	209 Posted in "Tons"		27 Tons
42 Type of Service	1 Highway - On	Appraisal		
	5 Waterway - Under	67 Structural Condition		4 Minimum Tolerable
28 Lanes on Structure	2	68 Deck Geometry		6 Equal Min Criteria
29 ADT	30 30 Year of ADT	69 Underclear Vert & Horiz		N Not applicable (NBI)
109 Average Daily Truck Traffic	2013	71 Waterway Adequacy		6 Equal Desirable
19 Bypass, Detour Length	2 Miles	72 App. Rdwy Alignment		6 Equal Min Criteria
Geometric Data		36 Traffic Safety Features		0 0 0 0
10 Min Vert Clearance	328 Ft. 1 in.	113 Scour Critical		U Unknown Scour
32 Approach Roadway Width	20 Feet	Inspections		
33 Bridge Median	0 No median	90 Date of Last Inspection		September 02, 2015
34 Skew	0.00	91 Designated Inspection Frequency		24 Months
35 Structure Fished	0 No bare	92 Critical Feature Inspected / 93 Critical Feature Last Inspection Ct		
47 Total Horizontal Clearance	25.3 Feet	Fracture Critical	N	
48 Length of Max Span	26 Feet	Underwater	N	
49 Structure Length	29.86 Feet	Other Special	N	
50 Curb/Sidewalk Widths	0.3 Ft Rt-Side	218 Channel Profile	Y 48	09/19/2013
	0.3 Ft Lt-Side	Chaining Date		None
51 Bridge Rdwy Width - Curb to Curb	25.3 Feet	207 Transporter Erector Routes and Sites		-1
52 Deck Width	26.2 Feet	212 Structure Load Rated		01/01/1901
53 Min Vert Clear. Over Bridge	328 Ft. 1 in.	213 Federal Aid Project Number		
54 Min Vert Underclearance	0.0 Ft. 0 in.	214 Delayed Inspection		Not Applicable

March 09, 2017

North Dakota Department of Transportation

Bridge Inventory - Structure Inventory And Appraisal Sheet

SEC 409

Structure Number: 05-147-19.0

200 System Designation	3 – County Off	Classification	
201 Status	Not Deficient	12 Base Highway Network	Not on Base Network
202 Sufficiency Rating	63.30	20 Toll	3 On free road
Identification		21 Maint Responsibility	02 County Hwy Agency
02 Highway District	Minot District	22 Owner	02 County Hwy Agency
03 County	Bottineau	26 Functional	Rural, Local
04 City	OAK VALLEY TOWNSHIP	37 Historical Significance	3 Possibly eligible for
05 Inventory Route	Route On Structure	100 Defense Highway Designation	0 Not a STRAHNET hwy
4 County Hwy 1 Mainline	00000 0 N/A (NBI)	101 Parallel Structure Designation	No bridge exists
06 Feats Intersect	DRAINAGE DITCH	102 Direction of Traffic	2 2-way traffic
09 Location	2 NORTH 1 EAST OF GARDENA	103 Temporary Structure Designation	Not Applicable (P)
11 Milepoint	0.000	104 Highway System of Inventory Rte	0 Not on NHS
13 LRS Inv Route. Subroute	-1 -1	105 Federal Lands Highways	Not applicable
16 Latitude	48d 44' 02.00"	110 Designated National Network	0 Not part of natl netwo
17 Longitude	100d 28' 53.00"	112 NBIS Bridge Length	Yes
GPS Coordinates XY	391084.1 5398918.9	Condition	
98 Border Bridge	Unknown (P) 0.00 %	58 Deck	7 Good
99 Border Bridge Struct No.	–	59 Superstructure	6 Satisfactory
Structure Type and Material		60 Substructure	6 Satisfactory

Structure Type and Material

43 Main Struct Type	Wood or Timber
Stringer	
44 Approach Struct Type	Unknown (NBI)
	Unknown (P)
45 No. Spans in Main Unit	2
46 No. Approach Spans	0
107 Deck Struct Type	8 Wood or Timber
108 Wearing Surface	8 Gravel
Membrane	0 None
Dk Protect	None
208 Dk Overburden	205 Gravel/Dir

Age and Service

27 Yr Built	1935	106 Yr Reconstructed	-1
42 Type of Service	1 Highway - On	5 Waterway - Under	
28 Lanes on Structure	2		
29 ADT	25	30 Year of ADT	2016
109 Average Daily Truck Traffic	-1.00		
19 Bypass, Detour Length	2 Miles		

60 Substructure	6 Satisfactory
61 Chan. & Chan. Protection	7 Minor Damage
62 Culvert and Retaining Walls	N N/A (NBI)

Load Rating and Posting

31 Design Load		Unknown
41 Structure Open, Closed or Posted		P Posted for load
63 Operating Rating Method		2 AS Allowable Stress
64 Oper. Rating	HS 11	19 Tons
65 Inventory Rating Method		2 AS Allowable Stress
66 Inv. Rating	HS 7	13 Tons
70 Bridge Posting		0 >39.9% below
209 Posted in "Tons"		10 Tons

Appraisal

67 Structural Condition	4 Minimum Tolerable
68 Deck Geometry	5 Above Tolerable
69 Underclear. Vert & Horiz	N Not applicable (NBI)
71 Waterway Adequacy	6 Equal Minimum
72 App. Rdwy. Alignment	7 Above Min Criteria
36 Traffic Safety Features	0 0 0 0

Geometric Data

113 Scour Critical

U Unknown Scour

10 Min Vert Clearance 99 Ft. 12 In.

32 Approach Roadway Width 16 Ft.

33 Bridge Median 0 No median

34 Skew 0.00

35 Structure Flared 0 No flare

47 Total Horizontal Clearance 23.0 Ft.

48 Length of Max Span 13 Ft.

49 Structure Length 29.86 Ft.

50 Curb/Sidewalk Widths 0.7 Ft Rt-Side

0.7 Ft Lt-Side

51 Bridge Rdwy Width - Curb to Curb

23.0 Ft.

52 Deck Width 24.3 Ft.

53 Min Vert Clear. Over Bridge 99 Ft. 12 In.

54 Min Vert Underclearance 0 Ft. 0 In.

N Feature not hwy or RR

55 Min Lateral UnderClear. - Rt 99.9 Ft.

N Feature not hwy or RR

56 Min Lateral UnderClear. - Lt 0.0 Ft.

210 Culvert / 211 Description

Inspections

90 Date of Last Inspection October 11, 2016

91 Designated Inspection Frequency 24 Months

92 Critical Feature Inspected / 93 Critical Feature Last Inspection Dt

Fracture Critical N

Underwater N

Other Special N

218 Channel Profile Y 48 08/16/2013

Chaining Date None

207 Transporter Erector Routes and Sites -1

212 Structure Load Rated 01/01/1901

213 Federal Aid Project Number

214 Delayed Inspection Not Applicable

216 Inspector Olson, Lawson

Navigation Data

38 Navigation Control Permit Not Required

39 Navigation Vertical Clearance 0 Ft.

40 Navigation Horizontal Clearance 0 Ft.

111 Pier or Abutment Protection Unknown (NBI)

116 Minimum Navigation Vertical Clearance -1 Ft.

Element Rating

Item or Defect	Condition States			
	1	2	3	4
	Good	Fair	Poor	Severe

Item or Defect	Condition States			
	1	2	3	4
	Good	Fair	Poor	Severe

March 09, 2017

North Dakota Department of Transportation

Bridge Inventory - Structure Inventory And Appraisal Sheet

SEC 409

Structure Number: 05-147-19.0

Element / Env. / Description	Units	Total Qty	1 %	1-Qty St	2 %	2-Qty St	3 %	3-Qty St	4 %	4-Qty St
111/1:Timber Open Girder	ft	689	0	0	98	676	2	13	0	0
1150/1:Check/Shake	each	676	0	0	100	676	0	0	0	0
1160/1:Crack (Timber)	each	13	0	0	0	0	100	13	0	0
206/1:Timber Column	each	18	0	0	100	18	0	0	0	0
1150/1:Check/Shake	each	18	0	0	100	18	0	0	0	0
216/1:Timber Abutment	ft	49	0	0	100	49	0	0	0	0
1150/1:Check/Shake	each	49	0	0	100	49	0	0	0	0
235/1:Timber Pier Cap	ft	72	0	0	100	72	0	0	0	0
1150/1:Check/Shake	each	72	0	0	100	72	0	0	0	0

31/1:Timber Deck	sq.ft	689	0	0	100	689	0	0	0	
332/1:Timb Bridge Railing	ft	59	0	0	49	29	0	0	51	30
1150/1:Check/Shake	each	29	0	0	100	29	0	0	0	
7000/1:Damage	each	30	0	0	0	0	0	0	100	30
8401/1:Wings	each	4	75	3	25	1	0	0	0	

Remarks: TIMBER CURBS HAVE MINOR TO MODERATE DAMAGE. TOPS OF WINGS HAVE MINOR SNOW PLOW DAMAGE. PLANK AT GIRDER ENDS HAS SLIPPED DOWN, ALLOWING SOIL TO BUILD UP ON ABUTMENT CAPS. ALL STRUCTURAL MEMBERS ARE WEATHER CHECKED. SILT BAR BUILDING UP IN WEST SPAN. GIRDER 17 FROM NORTH HAS LONGITUDINAL CRACK. GIRDER 13 HAS DEEP WEATHER CHECK. EAST ABUTMENT CAP HAS DEEP WEATHER CHECK ON ITS VERTICAL FACE. Pier 2 has minor damage at both ends from debris. West abutment bottom horizontal plank is cracked 3'-4', north end. Small void behind west abutment south end where ties to wing. NO END MARKERS.

Alert Code 1: Small sink holes at west end of bridge behind abutment in wheel paths.

Inspection Terms

- The **SUFFICIENCY RATING** of a bridge is a single number from 0 (low) to 100 (high) taking into account, bridge condition, geometry, traffic, and how well the waterway passes underneath the bridge. Sufficiency rating is used to determine funding eligibility. A low sufficiency rating does not necessarily mean the bridge is unsafe or in need of immediate repair.
- A **FRACTURE CRITICAL MEMBER** is a steel member in tension that does not have enough additional, structural members to sufficiently redistribute load in the bridge if one member loses capacity, thus resulting in a portion of or entire bridge collapse.
- **FATIGUE** is a material response that describes the tendency of a material to break when subjected to repeated loading.

Inspection Terms

- Bridges are considered **STRUCTURALLY DEFICIENT** if significant load-carrying elements are found to be in poor or worse condition due to deterioration and/or damage, or the adequacy of the waterway opening provided is determined to be extremely insufficient. The fact that a bridge is structurally deficient does not immediately imply that it is likely to collapse or that it is unsafe.
- Bridges are considered **FUNCTIONALLY OBSOLETE** when the geometry of the roadway no longer meets today's minimum design standards for width or vertical clearance for that roadway classifications, or the adequacy of the waterway opening provided is determined to be insufficient. The fact that a bridge is functionally obsolete does not imply that it is unsafe.

Sufficiency Rating

1. STRUCTURAL ADEQUACY AND SAFETY

$S_1 = 55\% \text{ Max.}$

- 59 Superstructure
- 60 Substructure
- 62 Culverts
- 66 Inventory Rating

2. SERVICEABILITY AND FUNCTIONAL OBSOLESCENCE

$S_2 = 30\% \text{ Max.}$

- 28 Lanes on Structure
- 29 Average Daily Traffic
- 32 Appr. Rdwy. Width
- 43 Structure Type, Main
- 51 Bridge Rdwy. Width
- 53 VC over deck
- 58 Deck Condition
- 67 Structural Evaluation
- 68 Deck Geometry
- 69 Underclearances
- 71 Waterway Adequacy
- 72 Appr. Rdwy. Align.
- 100 STRAHNET Highway Designation

3. ESSENTIALITY FOR PUBLIC USE

$S_3 = 15\% \text{ Max.}$

- 19 Detour Length
- 29 Average Daily Traffic
- 100 STRAHNET Highway Designation

4. SPECIAL REDUCTIONS

$S_4 = 13\% \text{ Max.}$

- 19 Detour Length
- 36 Traffic Safety Features
- 43 Structure Type, Main

$$\text{SUFFICIENCY RATING} = S_1 + S_2 + S_3 - S_4$$

Sufficiency Rating shall not be less than 0% nor greater than 100%

Drone Inspection Video

<https://www.youtube.com/watch?v=a4QcwQZPwCU>



UAV BRIDGE INSPECTION RESEARCH
THE BRIDGES








Underwater Inspections




Inspection Tool List

100 ft tape
Tape measure
4' level
Plumb bob
Range pole
Ladder
Magnifying glass
Flashlight
Binoculars

Hammer
First Aid Kit
Scraper
Shovel
Inspection forms
Camera
Paint
Lumber crayon




Poor alignment




Good alignment

Outlet Scour



Outlet Scour Treatment



Don't fill scour hole completely or erosion problem will reoccur



Bridge Photos – Photography 101



1. Roadway across Bridge



2. Side Elevation View



3. Underside View



Concrete Deck Overlays

Deck Overlays Cause Problems



A close-up photograph showing a person's hand lifting a thick, grey concrete slab. The slab is being lifted from a surface, revealing a dark, layered material underneath. The concrete slab has a rough, textured surface. The background is a dark, layered material, possibly a road base or a different type of concrete. The lighting is bright, casting shadows on the concrete slab and the layered material below.

Bonding Issues

Trapping Salts







Identify Joints

Finger Joints





Timber

Decay
Cracks




Look for
damage
and gaps





Bearings

Position is Important






Piling





Efflorescence –
leaching – stains



Alkali-Silica Reactivity (ASR)





ASR

Steel and Weathering Steel



Patina is flaking



Pack Rust Oxidation Corrosion



Pack Rust Expansion 7X







Concrete Delamination

Chaining & Delam Tool





Utilities





Key Terms and Topics

Bridge Length – Major and Minor
Structurally Deficient
Functionally Obsolete
Sufficiency Rating
SI&A Sheet



Inspections - Part #2 and Reporting Procedures



Paperwork

- Load Posting Requirement
- Alert Code 3 notification
- Scour & Channel Profiles Due
- Bridge Location Maps

TO: Bottineau County

FROM: Paul Benning, Local Government

DATE: March 31, 2017

SUBJECT: Bridge Requiring Load Limit Posting

Bridge Number: 05-157-28.0

Location: 2E OF WILLOW CITY

According to the latest bridge inspection and inventory data, 05-157-28.0 lacks proper Load Limit Signs. FHWA Regulations require that any bridge with an operating rating of less than legal loads must be posted for a Load Limit that does not exceed the Operating Rating. The legal load in North Dakota is an HS20 truck which weighs 36 tons. Since bridge number 05-157-28.0 is less than 36 tons, it must have Load Limit Signs.

Bridge number 05-157-28.0 has an Operating Rating of 17.0 Tons. It is your option to post the bridge at any tonnage you want as long as it is equal to or less than the maximum operating tonnage. Two types of signs (shown on attachment) are recommended in order to provide drivers with a more consistent messages statewide. Please complete the following after you have posted this bridge.

Bridge number 05-157-28.0 is posted at _____

Type of sign used (R12-1, R12-4, or Other) _____

Date Bridge was posted: _____

Other Remarks: _____

Work Done By Whom: _____

If you have any questions, please call me at 328-4334. Please Appreciated) to: _____

Local Government
ND Department of
608 East Boulevard
Bismarck, North D

TO: Bottineau County

FROM: Paul Benning, Local Government

DATE: March 31, 2017

SUBJECT: Bridge Requiring Load Limit Posting

Bridge Number: 05-157-28.0

Location: 2E OF WILLOW CITY

According to the latest bridge inspection and inventory data on record with the Bridge Division, bridge number 05-157-28.0 lacks proper Load Limit Signs. FHWA Regulations require that any bridge with an operating rating of less than legal loads must be posted for a Load Limit that does not exceed the Operating Rating. The legal load in North Dakota is an HS20 truck which weighs 36 tons. Since bridge number 05-157-28.0 is less than 36 tons, it must have Load Limit Signs.

Bridge number 05-157-28.0 has an Operating Rating of 17.0 Gross Tons and an Inventory Rating of 10.0 Gross Tons. It is your option to post the bridge at any tonnage you want as long as it is equal to or less than the maximum operating tonnage. Two types of signs (shown on attachment) are recommended in order to provide drivers with a more consistent messages statewide. Please complete the following after you have posted this bridge.

Bridge number 05-157-28.0 is posted at _____

Type of sign used (R12-1, R12-4, or Other) _____

Date Bridge was posted: _____

Tons

INSTRUCTIONS FOR POSTING WEIGHT LIMITS
ON
COUNTY BRIDGES

- Priority I Post all unposted bridges as soon as possible (data from last inventory provided).
- Priority II Update signs as conditions or re-rating change present weight limits.

NOTE: All bridges should be posted using one of the following sign types. Either the inventory ton or the operating ton is the maximum posting to be used. The choice of which one is left up to your discretion at each bridge site.

- A. The new rating is in the HS format (e.g. the first digit is a 2). If the last two digits are less than 36 and more than 21, then post by using sign R12-1.

Examples: Where range is above 21 or less than 36

WEIGHT LIMIT 22 TONS	WEIGHT LIMIT 22 TONS	WEIGHT LIMIT 22 TONS	WEIGHT LIMIT 22 TONS
-------------------------------	-------------------------------	-------------------------------	-------------------------------

(all are R12-1 24"x30")

- B. The new rating is in the HS format (e.g. the first digit is a 2). If the last two digits are 21 or less, then post by using sign R21-4.

Examples: Where range is 21 or less

WEIGHT LIMIT 2 TONS PER AXLE 5 TONS GROSS	WEIGHT LIMIT 5 TONS PER AXLE 12 TONS GROSS	WEIGHT LIMIT 9 TONS PER AXLE 21 TONS GROSS
---	--	--

[0.444x5=2 (max/axle)]

[0.444x12=5 (max/axle)]

[0.444x21=9 (max/axle)]

(All are R12-4 36"x24")



Alert Codes

FHWA requires that there is a follow-up procedure for bridges that have been identified with the alert code 3 status (immediate attention required). To comply with the FHWA requirement, NDDOT is requesting each owner of a bridge with an alert code 3 to use this report format to identify action taken to address the alert code 3 condition. This should be done by July 15, 2017. The following is the alert code remarks section from the Structure Inventory and Appraisal sheet for the subject bridge that requires attention:

TO: Dickey County
FROM: Paul Benning, Local Government
DATE: March 31, 2017

SUBJECT: Follow-up on Bridges with Alert Code 3 - IMMEDIATE ATTENTION

Bridge Number: 11-123-08.0

Location: 3 EAST 1 NORTH MONANGO

FHWA requires that there is a follow-up procedure for bridges that have been identified with the alert code 3 status (immediate attention required). To comply with the FHWA requirement, NDDOT is requesting each owner of a bridge with an alert code 3 to use this report format to identify action taken to address the alert code 3 condition. This should be done by July 15, 2017. The following is the alert code remarks section from the Structure Inventory and Appraisal sheet for the subject bridge that requires attention:

Remarks: NBI Remarks: Spalling thru-out structure. Exposed steel on east curb. West railing bent. Poor stream alignment. Road posted for 30 mph. Exposed rebar throughout structure exposed rebar west curb north end. .

Alert Code 3: 1/2016 - South diaphragm has a longitudinal crack.

Below describes what work or (repairs or other action) was done by the county to alleviate the cause of the alert code 3. Also describe any other work that you've done on this bridge that would affect the condition ratings or the load ratings.

Work Done By Whom: _____ On Date: _____

If you have any questions, please call me at 328-4334. Please return this form by July 15, 2017 (Earlier Response Appreciated) to:

Local Government Division
ND Department of Transportation
608 East Boulevard Ave.
Bismarck, North Dakota 58505-0700

Scour Surveys

Turned over to the
Counties in 1995 – WHY??

Required every 4 years

March 31, 2017

Bottineau County

North Dakota Department of Transportation
Bridge Inventory - Scour and Channel Profile

Page 5 of 54

SEC 409

Structure Number	Location	Feature Intersected	Channel Profile		Year Built	Structure Type
			Last Inspected	Frequency		
05-101-14.0	12 NORTH 4 WEST LANSFORD	WEST CUT BANK CREEK	08/23/2013	48	1945	Wood or Timber - Stringer
05-101-15.0	11 NORTH 5 WEST LANSFORD	CREEK	08/26/2013	48	1955	Concrete - Channel Bm
05-102-14.0	2 EAST 3 NORTH OF MOHALL	WEST CUT BANK CREEK	08/23/2013	48	1970	Concrete - Channel Bm
05-103-12.0	8 SOUTH 8 WEST ANTLE	CUT BANK CREEK	08/23/2013	48	1989	Prestressed conc - Adjacent Box Bm
05-103-15.0	3 EAST 2 NORTH OF MOHALL	CUT BANK CREEK	08/23/2013	48	1965	Concrete - Channel Bm
05-104-12.0	14 NORTH 1 WEST LANSFORD	CUT BANK CREEK	08/26/2013	48	1948	Wood or Timber - Stringer
05-105-14.0	12 NORTH 1 WEST LANSFORD	CUT BANK CREEK	08/23/2013	48	1970	Concrete - Channel Bm
05-107-08.0	8 SOUTH 3 WEST OF ANTLE	CREEK	08/23/2013	48	1935	Wood or Timber - Stringer
05-108-20.0	6 NORTH 3 EAST LANSFORD	CUT BANK CREEK	06/23/2014	48	1949	Wood or Timber - Stringer
05-108-21.0	8 WEST OF MAXBASS	CUT BANK CREEK	08/20/2013	48	1948	Wood or Timber - Stringer
05-109-01.0	2 NORTH 1 WEST OF ANTLE	ANTLE CREEK	08/23/2013	48	1939	Wood or Timber - Stringer
05-109-13.0	8 SOUTH OF ANTLE	CREEK	08/23/2013	48	1950	Wood or Timber - Stringer

March 31, 2017

Dickey County


North Dakota Department of Transportation
Bridge Inventory - Scour and Channel Profile

Page 12 of 54

SEC 409

Structure Number	Location	Feature Intersected	Channel Profile		Year Built	Structure Type
			Last Inspected	Frequency		
11-145-03.0	7 N 1 E OF OAKES	CREEK	06/12/2013		1976	Prestressed conc - Tee Bm

County Structures Due for Channel Profile: 1



North SIDE

NDSU

Bridge Inspection

County pays 19.07% match for
NDDOT inspection =
\$45.20/structure

Box Culvert Inspection Cycle

January 13, 2016

North Dakota Department of Transportation Bridge Inventory - Structure Inventory And Appraisal Sheet

SEC 409

Structure Number:	16-113-28.1	chaindate	
200 System Designation:	3 - County Off	Classification	
201 Status	Not Deficient	12 Base Highway Network	Not on Base Network
202 Sufficiency Rating	62.00	30 Toll	3 On free road
Identifications		21 Maint Responsibility	02 County Hwy Agency
02 Highway District	Grand Forks District	22 Owner	02 County Hwy Agency
03 County	Gr. Forks	26 Functional	Rural, Local
04 City	GRACE TOWNSHIP	37 Historical Significance	5 Not eligible for NRHP
05 Inventory Route	Route On Structure	100 Defense Highway Designation	0 Not a STRAHNET Hwy
4 County Hwy 1 Mainline	00000 0 N/A (NBI)	101 Parallel Structure Designation	No bridge exists
06 Feats Intersect	CREEK	102 Direction of Traffic	2 2-way traffic
09 Location	2 SOUTH 1 WEST KEMPTON	103 Temporary Structure Designation	Not Applicable (P)
11 Milepoint	0.000	104 Highway System of Inventory Rte	0 Not on NHS
13 LRS Inv Route: Subroute	-1 -1	105 Federal Lends Highways	Not applicable
16 Latitude	47S 47' 16.00"	110 Designated National Network	0 Not part of natl network
17 Longitude	97S 36' 36.00"	112 NBS Bridge Length	
GPS Coordinates XY	601621.7 5203501.9	226 Functional Under	
36 Border Bridge	Unknown (P)	Condition	
39 Border Bridge Struct No.	-	58 Deck	7 Good
Structure Type and Material		59 Superstructure	8 Satisfactory
40 Main Struct Type	Steel	60 Substructure	5 Fair
41 Main Struct Type	Stringer	61 Chas. & Chan. Protection	7 Minor Damage
44 Approach Struct Type	Unknown (NBI)	62 Culvert and Retaining Walls	N/A (NBI)
45 No. Spans in Main Unit	1	Load Rating and Posting	
46 No. Approach Spans	0	31 Design Load	M 18 (H 20) (live load for which structure was designed)
107 Deck Struct Type	8 Wood or Timber	41 Structure Open, Closed or Posted	P Posted for load
108 Weaving Surface	7 Wood or Timber	63 Operating Rating Method	2 AS Allowable Stress
Membrane	0 None	64 Oper. Rating	HS 14 26 Tons
DK Protect	None	65 Inventory Rating Method	2 AS Allowable Stress
206 Dk Overburden	205	66 Inv. Rating	HS 0 17 Tons
Age and Service		70 Bridge Posting	2 20.0-25.9kbelow
27 Yr Built	1949 105 Yr Reconstructed	209 Posted in "Tons"	27 Tons
42 Type of Service	1 Highway - On	Appraisal	
28 Lanes on Structure	5 Waterway - Under	67 Structural Condition	4 Minimum Tolerable
29 ADT	30 30 Year of ADT	68 Deck Geometry	6 Equal Min Criteria
109 Average Daily Truck Traffic	-1.00	69 Underclear: Vert & Horiz	11 Not applicable (NBI)
19 Bypass, Detour Length	2 Miles	71 Waterway Adequacy	8 Equal Desirable
Geometric Data		72 App. Rdwy. Alignment	8 Equal Min Criteria
10 Min Vert Clearance	328 Ft. 1 in.	36 Traffic Safety Features	0 0 0 0
32 Approach Roadway Width	20 Feet	113 Scour Critical	U Unknown Scour
33 Bridge Median	0 No median	Inspections	
34 Skew	0.00	90 Date of Last Inspection	September 02, 2015
35 Structure Flared	0 No flare	91 Designated Inspection Frequency	24 Months
47 Total Horizontal Clearance	25.3 Feet	92 Critical Feature Inspected / 93 Critical Feature Last Inspection CH	
48 Length of Max Span	26 Feet	Fracture Critical	N
49 Structure Length	28.86 Feet	Underwater	N
50 Curb/Sidewalk Widths	0.3 Ft Rt-Side	Other Special	N
	0.3 Ft Lt-Side	218 Channel Profile	Y 48 09/19/2013
51 Bridge Rdwy Width - Curb to Curb	25.3 Feet	Chemical Date	None
52 Deck Width	26.2 Feet	207 Transporter Erector Routes and Sites	-1
53 Min Vert Clear. Over Bridge	328 Ft. 1 in.	212 Structure Load Rated	01/01/1901
54 Min Vert Underclearance	0 Ft. 0 in.	213 Federal Aid Project Number	
N Feature not Hwy or RR		214 Delayed Inspection	Not Applicable
55 Min Lateral UnderClear. - Rt	327.6 Feet	216 Inspector	Fischer
N Feature not Hwy or RR		Navigation Data	
56 Min Lateral UnderClear. - Lt	0.0 Feet	36 Navigation Control	Permit Not Required
219 Culvert / 211 Description		39 Navigation Vertical Clearance	0 Feet
		40 Navigation Horizontal Clearance	0 Feet
		111 Pier or Abutment Protection	Unknown (NBI)
		115 Minimum Navigation Vertical Clearance	-1 Feet

Key Terms and Topics

Guardrail Requirements

Critter Crossings

New/Rehabilitated/Repaired Bridges

Historical Bridge

Guardrail Clear Zone



Table 1 CLEAR ZONE DISTANCE (in Feet from Edge of Driving Lane)¹

DESIGN SPEED	DESIGN ADT***	FORESLOPE					BACKSLOPE				
		FLAT	1V: 6H	1V: 5H	1V: 4H	1V: 3H	1V: 3H	1V: 4H	1V: 5H	1V: 6H	FLAT
40 mph or less	Under 750	7-10	7-10	7-10	7-10	**	7-10	7-10	7-10	7-10	7-10
	750-1500	10	12	12	14	**	12-14	12-14	12-14	12-14	12-14
	1500-6000	12	14	14	16	**	14-16	14-16	14-16	14-16	14-16
	Over 6000	14	16	16	18	**	16-18	16-18	16-18	16-18	16-18
45-50 mph	Under 750	10	12	12	14	**	8-10	8	10	10	12
	750-1500	14	16	16	20	**	10-12	12	14	14	16
	1500-6000	16	18	20	26	**	12-14	14	16	16	18
	Over 6000	20	22	24	28	**	14-16	18	20	20	22
55 mph	Under 750	12	14	14	18	**	8-10	10-12	10-12	10-12	10-12
	750-1500	16	18	20	24	**	10-12	14	16	16	18
	1500-6000	20	22	24	30	**	14-16	16	18	20	22
	Over 6000	22	24	26	32*	**	16-18	20	22	22	24
60 mph	Under 750	16	18	20	24	**	10-12	12	14	14	16



State of the Guardrail Industry: Advances in Longitudinal Barrier Design

Bob Bielenberg

**Midwest Roadside Safety
Facility
University of Nebraska-Lincoln**

**NDLTAP Video Conference
February 18, 2015**



Increased Rail Height

- Improved capture
- Reduced rollover potential



Test No. MGSBR-1

- MASH
 - 3-11
 - 2270P
- Impact conditions
 - 61.9 mph
 - 24.9 deg.
- Dynamic deflection
 - 48.9 in.




Test No. MGSBR-1



Test No. LSC-2

- 2,261-kg Dodge Quad Cab
- 99.6 km/h - 24.9 degrees





Critter Policies



Animal Crossings

We all have them



Moose Crossing






New Bridge Process



Bridge Removal Process

NDSU UPPER GREAT PLAINS
TRANSPORTATION INSTITUTE



Structure Inspection Notification

County			
Structure Number			
Location			
Reason for inspection (new/rehabilitation/repair)			

Who performed the work?			
Was Structure previously closed? (y/n)		If so, when?	
Date work was completed		Currently posted for Load? (y/n)	

Location of Work Performed

Work performed on the following areas of the Structure			
Deck (y/n)		Pier(s) (y/n)	
Beam/Girder (y/n)		Abutment(s) (y/n)	
Pier/Abutment Caps (y/n)		Channel (riprap) (y/n)	
Other			

Was the work completed due to an Alert Code on the SI&A sheet (y/N)	
If yes, what Alert Code was repaired	

What work was completed on this Structure

--

Materials used (provide a description of the material properties, size, etc.)

Flood Plan of Action

When to check
What bridges to check
When to close
Who to Inform
Actions to Save Bridge

TOP STORY



<http://www.myndnow.com/news/minot-news/bridges-destroyed-in-bottineau-county-flooding/686441852>



TOP STORY Bottineau County Flooding



TOP STORY



TOP STORY



TOP STORY Rich Gimbel
BOTTINEAU COUNTY ROAD SUPERINTENDENT





[illegible]

The Viking Bridge, previously known as the Goose River Bridge, was the Trail County Commission's top road improvement priority in 1985. Because the Goose River divides Mayville and Portland was a major obstacle to commerce. This bridge provided a vital transportation link between the two towns. In 1910, the firm Jardine and Anderson moved the bridge from its crossing on the Mayville - Portland road to this location in Viking Township. Concrete abutments and steel reinforcing girders strengthened the structure. This bridge was originally built in 1924. In 1985 and 30 years later was moved.

By the 1860s, metal truss bridges were commonly used throughout the country, and had replaced earlier bridges (with the exception on the smallest spans). Metal truss bridges were one of the first industrial engineered technologies (with the exception of the "iron horse" passenger) that facilitated new populations moving into North Dakota. Infrastructure, rather than "horse" or "team" based economies, although there was limited water transportation earlier, and the establishment of new farm-based economies. In 1881, a web of metal transportation had to be developed and ultimately resulted in the state beginning in 1888, a web of metal transportation had the advantage of being developed to move bulk commodities to markets. Metal truss bridges had the advantage of being mass-produced in Wisconsin and Eastern cities, transported by railroad in compact form close to a site, and then quickly assembled on site by local unskilled labor to replace a bridge company foreman. Timber or stone bridges would have required a more skilled labor and much more time to erect.

[illegible]

IKING

Oldest Documented Vehicle Bridge in North Dakota

- 110' long
- 24' high
- 15'6" roadway width
- Originally built in 1885 for \$8,294
- Relocated in 1915 for \$2,138
- Closed to traffic in 2006
- Rehabilitated in 2010 for \$529,912
- 2010 Rehabilitation Project Funded by the American Recovery and Reinvestment Act of 2009 (ARRA)

- 110' long
- 24' high
- 15'6" roadway width
- Originally built in 1885 for \$8,294
- Relocated in 1915 for \$2,138
- Closed to traffic in 2006
- Rehabilitated in 2010 for \$529,912
- 2010 Rehabilitation Project Funded by the American Recovery and Reinvestment Act of 2009 (ARRA)

The Viking Bridge, the oldest documented vehicle bridge in North Dakota, was closed to traffic in the fall of 2006 due to its poor condition. Several of the truss components had been damaged by river debris and vehicles, the timber deck had deteriorated, and the south abutment had been undermined by river erosion. In June of 2010, a rehabilitation project began to restore the bridge for continued use as a vehicular bridge. The project included moving the bridge approximately 10 feet south to better fit the river channel and construction of new concrete abutments. It also included repair and replacement of damaged steel components, new bridge pins, a new timber deck and curb system. In October 2010, the project was completed and the bridge reopened to traffic.

PROJECT PARTNERS:

Trails County Commission
North Dakota Department of Transportation
Federal Highway Administration
Contractor - On The Level Construction, Inc.
Engineer - Kadmas, Lee & Associates

Key Terms and Topics

Who can close a bridge?

Flood Action Plan

Clear Zones

Reporting for Closed, repaired or new bridges



Failures



Frost Heaves

*Frost Damage in Pavement:
Causes and Cures* (You Tube video)

Sample expanded
from 6 to 10 inches
Total Heaving: 70%



<https://www.youtube.com/watch?v=7gjtFaCxVRU>

Press Esc to exit full screen

FROST DAMAGE IN PAVEMENT: Causes and Cures



Flow Rate of Water – Velocity Checks

Bridge - 5 feet per second

Culvert – 10 feet per second

(USFS uses 7 fps in the Badlands)

Walk = 3 mph = 4.5 feet per second

Jog = 5 mph = 7 feet per second

Run = 10 mph = 15 feet per second







Oil Patch bridge not the only one taking a beating

By Kathleen J. Bryan, Forum News Service on Dec 7, 2014 at 11:25 p.m.

WATFORD CITY, N.D. – Mauricio Gomez drove a truck more than 1,500 miles from Houston hauling pipe to North Dakota's Oil Patch only to find the bridge on a main traffic route closed, creating a detour that added another 100 miles to his trip.

A load being hauled by another driver had struck the overhead framing on the Long X Bridge on U.S. Highway 85 south of Watford City, forcing it to close.

The Nov. 22 accident was not the first time an oversized load had damaged the 55-year-old bridge,



The most recent hit on the Long X Bridge near Watford City came Nov. 22 when an excavator on a trailer hit the bridge's overhead framing. Special to The Forum








A wooden walking bridge over the Sheyenne River in Lisbon, N.D., is a twisted mess Thursday, Sept. 25, 2008, after it collapsed Wednesday, injuring five construction workers who were taking a break on the bridge. Authorities said two of the men were treated and released and three others were taken to Fargo hospitals. No names or conditions were immediately available. (AP Photo/The Forum, Dave Wallis)





The Bismarck Tribune

Rewriting legislation

Senate Bill 2344 would change language of Measure 5

DAKOTA, BI



B
St
Me



SUNNY 15 • 6

FORECAST, B6

FRIDAY, FEBRUARY 3, 2017

bismarck



TOM STROMME PHOTOS, TRIBUNE

Truck with an oversize load struck the underside of a bridge over Interstate 94 near mile marker 129 on Wednesday, leaving extensive damage to the underside of the overpass near McKenzie. The bridge, closed indefinitely until repairs can be made, carried local traffic on 25th Street Northeast in rural McPherson County.

Truck crashes into bridge



9-12-03
Traill Co. Br.





McHenry County 2014



Fire Damage



Fire – above and below



DAVID GOLDMAN, ASSOCIATED PRESS

Atlanta firefighter Latoya Bailey jumps over a highway divider Friday while working the scene where a section of an overpass collapsed from a large fire on Interstate 85 in Atlanta.

Highway collapse could snarl traffic for months

Atlanta's dreadful rush hour to get even worse through heart of city

KATE BRUNSWICK and MEL BARNOW
Associated Press

ATLANTA — Atlanta's dreadful rush-hour traffic could be extra nasty for months to come after a raging fire underneath Interstate 85 collapsed an elevated portion of the highway and shut down the heavily traveled route through the heart of the city.

Traffic was bumper to bumper on nearby streets as drivers were forced to take a detour Friday, the morning after the blaze caused the concrete to crumble.

The collapse took place a few miles south of downtown, and the effects

could fall most heavily on commuters from Atlanta's densely populated northern suburbs. They will have to find other routes to work or ride mass transit.

Connie Bailey-Blake, of Decatur, 37 miles northeast of Atlanta, waited for a MARTA commuter train to reach her job downtown. She typically drives, often by way of the interstate.

"I'm supposed to be at work at 9 a.m. and it's 9:15 a.m.," Bailey-Blake said. "The first few days are going to be difficult. This will be my new life."

Atlanta Ford picked a new route to work by car and said it took her 45 minutes to travel 3 miles from her Atlanta home to the nearest open on-ramp to the interstate.

Georgia Transportation Commissioner Russell McMurtry said 350 feet of highway will need to be


replaced in both directions on I-85, which carries about 400,000 cars a day through the city and is one of the South's most important north-south routes.

He said repairs will take months but declined to be more specific.

"The collapse effectively 'puts cork in the bottle,'" Georgia State Patrol Commissioner Mark McDonough said.

The fire broke out Thursday afternoon in an area used to store state-owned construction materials and equipment, sending flames and smoke high into the air. Fire author- ities said they had not determined how the blaze started.

McMurtry said his department stored coils of plastic conduit used in fiber optic networks beneath the span but insisted they were not a combustible.



Courtesy of Morton County Sheriffs Office

Posted: Wed 7:57 AM, Dec 21, 2016



MORTON CO., N.D. (KFYR) Nearly two months after it was damaged and closed to traffic, Gov. Doug Burgum announced that the North Dakota Department of Transportation will inspect damage to the Backwater Bridge in southern Morton County.

Parts of Highway 1806 and the bridge have been closed since Oct. 27 when protesters blocked it with burning vehicles.

North Dakota DOT and law enforcement agencies have said the bridge is unsafe for travel.

The DOT says results of the tests are expected 30 days after they are completed.

APRIL 4, 2017 - BISMARCK TRIBUNE



'97 4 18



Stark County Bridge Replacement





Bridge in rural N.D. collapses under weight of truck

By Forum News Service Today at 6:28 a.m.

64











A photograph of a road intersection. In the foreground, a metal signpost holds two signs. The top sign is rectangular with a black border and white background, reading "AXLE WEIGHT LIMIT 3 TONS". Below it is a smaller, rectangular sign with a red border and white background, reading "PASSENGER VEHICLES ONLY". Above the signs, two red flags are mounted on poles that angle outwards. The road is a light-colored gravel or dirt path that curves to the left. The background features a line of green trees, a yellow house on the left, and a large, open field on the right. A power line tower is visible in the distance under a cloudy sky.

AXLE
WEIGHT
LIMIT
3 TONS

PASSENGER
VEHICLES
ONLY



Don't Text and Drive

Safety reminder brought to you by your friends at NDLTAP and the NDDOT.



Bridge Preservation



What is Bridge Preservation?

AASHTO defines Bridge Preservation [as]
“actions or strategies that prevent, delay or reduce deterioration of bridges or bridge elements, restore the function of existing bridges, keep bridges in good condition and extend their life.”

Source: AASHTO Board of Directors, Policy Resolution PR-3-11, October 17, 2011.



Life Cycle Costs => Bridge Preservation




Construction Costs

Maintenance Costs



Salvage Value






Debris inhibits deck drainage.

Standing water promotes deck deterioration.

Water and deicers corrode steel reinforcement, causing spalling.

Speed, surface roughness and truck suspension interact to amplify stress.

Bridge superstructure is susceptible to corrosion, water damage, metal fatigue and stress caused by vibration



Debris-clogged joint prevents movement necessary to relieve superstructure stresses.

Improper drainage causes damage to concrete.

Crack in substructure caused by settling of foundation.

Surface corrosion

Water movement can scour away soil under foundation.

Decay or misalignment of bearings

Scheduled Maintenance

- Sweeping & Washing Decks
- Cleaning joints
- Cleaning drains
- Crack sealing decks
- Cleaning & lubricating bearings

Bridge Maintenance checklist

No.	Description	Frequency
1	Debris Removal	As Needed
2	Mechanical Sweeping	Spring and as needed
3	Cleaning of Abutment & Pier Tops	Annually
4	Cleaning of Elastomeric Expansion Joints (4 each)	Spring and as needed
5	Cleaning and Repair of Drainage system (68 Ea.)	Spring, Fall and as needed
6	Cleaning & Washing of Bridge (includes Washing of beams, walkways etc)	Annually
7	Cleaning and Lubrication of Bearings	Annually after No. 4&6
8	Patching of Sidewalks	Annually
9	Repair of Sidewalk Barrier	Annually
10	Patching and crack repair in Jersey Barriers	As Needed
11	Crack Sealing in Pavement & Curblines	Annually
12	Maintenance of Electrical Systems	As Needed
13	Repair of Wearing Surface/Overlays	Every 3-5 years
15	Painting of Steel (Full Bridge)	Every 30 years
14	Spot Painting 1	8 yrs. after No. 10
15	Spot Painting 2 (Painting of Salt Splash Zone and at bearings)	16 yrs. after No. 10
17	Spot Painting 3	24 yrs. after No. 10

Bridge Cost Estimates



New bridge - \$200/sf

Deck replacement - \$75/sf

Treat deck with silane - \$0.25/sf

Crack seal deck - \$0.10/sf

Risk Management



See no Evil



Williams County Asset Values

67 bridges => \$35 million

251 miles of paved road => \$251 million

79 miles of AST => \$59 million

497 miles of gravel road => \$250 million

Sum = \$595 million



Sand and
debris
holding
water on
deck

Keep It Clean!





Concrete Deck Maintenance



Deck Surface Treatment (Silane)





Box Beam Weep Hole



Cracked Beam – plugged weep hole





Bearing
Maintenance



Timber Deck Maintenance







Erosion Issues



Key Terms and Topics

Crack Sealing
Life Cycle
Bridge Preservation



Solutions



Alternatives

Load Restrictions
Temporary Bridges
Single Lane Bridges
Bridge/Road Closure
Use of Low-Water Crossings
Structural Repairs
Reusing Structural Members
ABC and Modular Units
GRS- IBS Abutments
Buried Bridges.

Prior to ALL Bridge Work



Know what's below.
Call before you dig.



**NORTH DAKOTA
ONE-CALL**
CALL 48 HOURS
BEFORE YOU
DIG - DRILL - BLAST

- | | |
|---------------------|-----------------------------|
| Electric | Reclaimed Water, Irrigation |
| Gas-Oil-Steam | Sewer |
| Communications/CATV | Temporary Survey Markings |
| Water | Proposed Excavation |

811 or 1-800-795-0555
www.ndonecall.com



A photograph of a concrete low water crossing structure over a stream. The structure consists of a wide, flat concrete slab supported by several concrete piers. The water is calm and reflects the surrounding greenery. The foreground is a gravelly bank, and the background is a dense forest of green trees. The text "Low Water Crossings" is overlaid in yellow on the lower part of the image.

Low Water Crossings






Accelerated Bridge Construction Using Steel Sheet Piles

In the United States, the use of steel sheet pile in accelerated bridge construction (ABC) dates back more than 15 years. The use of sheet piles

in civil engineering and public works has become a popular alternative to traditional methods.

Due to innovations in the manufacturing of steel and improvements of steel grades and composition, along with the enhanced availability of corrosion protection methods, steel sheet piles such as



This is an example of an accelerated bridge construction utilizing permanent steel sheet piles supplied by Skyline

Trends




Geosynthetic Reinforced Soil-Integrated Bridge System

The Geosynthetic Reinforced Soil-Integrated Bridge System (GRS-IBS) is an innovation to help reduce bridge construction time and cost. GRS-IBS projects can be built in weeks instead of months, due to the ease of construction and the use of readily available materials and equipment. Reduced construction schedule translates into less exposure around work zones improving safety.

GRS - IBS







Typical Section of a GRS/IBS Bridge Abutment
“ABC—Experience in Design, Fabrication, and Erection of PBES”

Geosynthetic Reinforced Soil Integrated Bridge System

GRS-IBS

Why Consider the GRS IBS?

Lower costs

Accelerated bridge construction

Smooth transition eliminating the “bridge bump”

FIBERGLASS REINFORCED POLYMER (FRP) DECK PANELS

Description:

These panels are much like the partial- and full-depth precast deck panels previously discussed. However, they are constructed from fiberglass reinforced polymer rather than concrete. The polymer is reinforced with fiber or some other material of equal strength to reinforce the panels in one or more directions along the span of the bridge.





*18" x 30" x 16' Pre-engineered SuperSill[®] abutment system
ready to be filled with concrete.*

(ABC-Accelerated Bridge Construction) & Modular Units





Vibratory Piling Driver



Railroad car bridge - temporary



**DEVELOPMENT OF LOAD RATING PROCEDURES FOR
RAILROAD FLATCARS FOR USE AS HIGHWAY
BRIDGES BASED ON EXPERIMENTAL AND
NUMERICAL STUDIES**

PHASE III FINAL REPORT-

*Prepared for
The Indiana Local Technical Assistance Program (LTAP)*

Types of Cars

Pulp Cars

Military

89' Flatcars, Cost \$19,000 (?) Delivered

89' Flatcar cut to 68', Cost \$16,667 Delivered

Total Costs range between \$65,000 and \$95,000

Flatcars
NOT
Boxcars





Railroad Flatcar Bridges

<https://www.youtube.com/watch?v=GEw2Yxlfljg>



Barnes County – Timber Box Culvert



Richland County Bridge









Stark County Bridge Replacement











Bridge # 46-120-04.0
Direction: Up
Far North Deck Patch (2 in Deck)
02/15/05

This image shows a close-up view of a bridge deck repair. It features several vertical steel plates, each secured with multiple bolts. The plates are arranged in a row, and the surrounding concrete structure is visible. The steel shows signs of rust and wear.




21-141-19.0 3-7-07
DECK REPAIRED WITH CUT
EDGES PICT # 28

This image shows a wider view of a bridge deck repair. It displays a series of horizontal steel plates laid out on a concrete surface. The plates are arranged in two rows, and the surrounding concrete is visible. The steel shows signs of rust and wear.

Post-tension Wood Deck - Michigan



- Over time nails back out and timbers spread



Spread Laminates






Load Test




	West Fascia	4' West	8' West	Centerline	8' East	4' East	East Fascia
Baseline	34 1/4	33 5/8	32 3/4	32 1/8	31 5/8	31 1/4	30 5/8
Test 1	34 1/8	33 5/8	32 3/4	32 1/8	31 1/2	31	30 1/2
Test 2	34 1/8	33 5/8	32 1/2	31 7/8	31 3/8	31 1/4	30 5/8
Test 3	34	33 3/8	32 1/2	32 1/8	31 1/2	31 3/8	30 5/8

1/4" Max Deflection (Greater than 50% Reduction)

Structure #: 34-112-03.0
Pier Unevenly Loaded with
Embankment and Riprap
Causing Horizontal Cracking
in Pier
Face South
Date 11/13/2006



Bridge # 32-119-85.0
Direction: North
Sediment and Tree Debris
Built Up Against West Side of
Pier. Note Farmers Fence Across
Channel Span
02/25/05



Structure # 50-153-22.0
Another View
Face NE
Date: 09/18/2007



Debris accumulation may cause lateral pressure and scour.

Water











New steel pile.
rt-new
It slipped over
old wood pile

11.13.2006



Plates welded to rusted pile

The photograph shows a vertical metal pile, likely steel, that is heavily corroded and rusted. Two vertical plates have been welded to the pile to repair a section of the web. The background is a light-colored, possibly sandy or silty, surface. The image is framed by a dark green border with white curved lines in the corners.

12/14/2006

9-106-19.0
11-22-2006
PILE WEB REPAIR
LOOKING SOUTH

Beam Seat Failure









Shot Crete





Abutment Repair



Pedestal Repair

















Grand Forks County Tips

Rip Rap
Sign

Treat timber ends
Keep wooden deck timbers tight































Glue Laminated Beams



Williams County Action Plan 2016

Major Structures

- Provide an evaluation/interpretation based on NDDOT FHWA/NBIS and field visit for each major structure

Minor Bridges

- Perform a full FHWA/NBIS inspection and provide an evaluation/interpretation for each minor bridge

Scour and Channel Profile

- Perform a scour and channel profile evaluation, completing NDDOT Form SFN 50344) for all major and minor bridges crossing water

Culvert Evaluation

- Perform a full evaluation on select minor culverts with significant concerns and prepare a report with findings, recommendations, and costs estimates

GIS Database

Key Terms and Topics

Local Solution Examples
Preserve What We Have
Solve Small Problems

Truck Overweight Permit System



Next up: Bridge Inspections





Williams County Field Inspections





Resource List

NDDOT Design Manual – Chapter 5

NDDOT Local Government Manual

NDDOT Bridge Inspection Team

ND Township Officers Manual

State Stream Standards

NDLTAP Resource Page

Ndltap.org

Your one stop shop for local road info

Tap into NDDOT and NDLTAP
We Want to Help!

Better roads save lives

Together, we can do great things. Please tap into the NDLTAP and NDDOT teams. We look forward to expanding a partnership that elevates the knowledge of all those that touch our transportation network and helps all of our friends and family return home safely every day.

Respectfully,

Dale C. Heglund, NDLTAP Program Director
701-318-6893 – dale.heglund@ndsu.edu
www.ndltap.org



Gary L. Doerr, PE

Bridge Management Team Leader, NDDOT



Dale C. Heglund, PE/PLS

Program Director, NDLTAP

Bridge 101

Grand Forks, June 6, 2018

Williston, June 13, 2018



Bryon Fuchs, PE

Local Government, NDDOT